

Survey of Scientific & Engineering Research Facilities

FY2013

Admin Unit	Department	Building	Net Area	Condition of Space								
				% Superior	% Satisfactory	% Requires Renovation	% Requires Replacement	Animal Space? Y/N	% Animal Space Used for Clinical Trials? Y/N	% Used for Clinical Trials		
<b>VC-Agriculture</b>			<b>157,412</b>									
<b>0700 - VICE CHANCELLOR-AGRICULTURE</b>			<b>10,415</b>									
		1507 - BIOCHEMISTRY/BIPHYSICS BLDNG	800		100			N		N		
		1536 - AGRILIFE SERVICES BUILDING	930	100				N		N		
		1538 - THE AGRILIFE CENTER	1,523	100				N		N		
		1605 - CENTEQ BUILDING	7,162		100			N		N		
<b>0701 - AGRILIFE ADMINISTRATIVE SERVICES</b>			<b>4,526</b>									
		1536 - AGRILIFE SERVICES BUILDING	4,526	100				N		N		
<b>0705 - TALR-ADMINISTRATION</b>			<b>6,852</b>									
		1535 - AGRICULTURE AND LIFE SCIENCES BUILDING	1,834	100				N		N		
		1605 - CENTEQ BUILDING	2,155		100			N		N		
		2944 - SCIENCE PARK BUILDING	2,863		100			N		N		
<b>0715 - Texas A&amp;M Institute of Genomic Medicine</b>			<b>25,263</b>									
		1900 - TEXAS A&M INSTITUTE FOR GENOMIC MEDICINE	25,263	100				Y	90	N		
<b>0720 - TALR-INSTITUTE OF RENEWABLE NATURAL RESOURCES</b>			<b>2,590</b>									
		1605 - CENTEQ BUILDING	2,590		100			N		N		
<b>0725 - TALR-FARM RESEARCH SERVICE</b>			<b>39,865</b>									
		0040 - FARM SERVICE OFFICE BLDG	1,460	10	80	10		N		N		
		0041 - FARM SERVICE LAB & OFFICE	1,008		50	50		N		N		
		0042 - FARM SERVICE EAST WING	4,056		50	50		N		N		
		0043 - FARM SERVICE MAINT SHED	1,584		50	50		N		N		
		0044 - FARM SERVICE CHEMICAL STORAGE	1,128		80	20		N		N		
		0045 - FARM SERVICE WEST WING SHED	3,192		50	50		N		N		
		0046 - FARM SERVICE NORTHWEST SHED	1,224		50	50		N		N		
		0050 - FIELD LAB EQUIPMENT SHED	7,200		30	70		N		N		
		0051 - FIELD LAB IMPLEMENT SHED	4,000		50	50		N		N		
		0054 - SAMPLE PROCESSING LABORATORY	1,944		20	80		N		N		
		0055 - STORAGE SHED	2,142		30	70		N		N		
		1001 - FARM SERVICE IMPLEMENT #1	1,513		50	50		N		N		
		1002 - FARM SERVICE IMPLEMENT #2	5,450		50	50		N		N		
		1003 - FARM SERVICE SHOP	3,964		50	50		N		N		
<b>0727 - TALR VEGETABLE IMPROVEMENT CENTER</b>			<b>4,641</b>									
		1605 - CENTEQ BUILDING	4,641		100			N		N		
<b>0730 - TALR-INSTITUTE FOR OBESITY RESEARCH</b>			<b>2,379</b>									
		1605 - CENTEQ BUILDING	2,379		100			N		Y		15
<b>0732 - INSTITUTE FOR COUNTERMEASURES AGAINST BIO. TERROR</b>			<b>2,685</b>									
		1605 - CENTEQ BUILDING	2,685		100			N		N		
<b>0740 - INSTITUTE FOR PLANT GENOMICS &amp; BIOTECH.</b>			<b>50,185</b>									
		1512 - Southern Crop Improvement Greenhouse	19,467	10	20	50	20	N		N		
		1513 - BORLAUG CENTER FOR SOUTHERN CROP IMPROVEMENT	30,717		60	20	20	N		N		
<b>0745 - TALR-TX WATER RESOURCES INSTITUTE</b>			<b>3,536</b>									
		1605 - CENTEQ BUILDING	3,536		100			N		N		
<b>0748 - TALR-INTERNATIONAL AGRI PROGRAMS</b>			<b>1,744</b>									
		1536 - AGRILIFE SERVICES BUILDING	1,744	100				N		N		
<b>0755 - TALX-AGRICULTURAL COMMUNICATIONS</b>			<b>1,479</b>									
		1536 - AGRILIFE SERVICES BUILDING	1,479	100				N		N		
<b>0780 - TALX-INFORMATION TECHNOLOGY</b>			<b>1,254</b>									
		1535 - AGRICULTURE AND LIFE SCIENCES BUILDING	167	100				N		N		
		1536 - AGRILIFE SERVICES BUILDING	1,087	100				N		N		
<b>Grand Total</b>			<b>157,412</b>									

Number of hours to complete this survey (rounded to nearest hour)

4



Signature of CEO

Date